Published on *Hunter Industries* (http://www.hunterindustries.com)

Prodotti: PGJ, [1]
SRM, [2]
PGP-ADJ, [3]
PGP Ultra, [4]
I-20, [5]
I-25, [6]
I-35, [7]
I-40 [8]

Argomenti: Risoluzione problemi, Video

Gli irrigatori a turbina Hunter girano grazie ad un sistema interno di ingranaggi attivato da una turbina messa in moto dal passaggio dell'acqua. Questo moto fa ruotare la torretta. Questo meccanismo ad ingranaggi è protetto contro lo sporco ed i detriti. Pressione eccessiva, acqua di scarsa qualità o un uso prolungato nel tempo possono far si che dello sporco si accumuli tra gli ingranaggi.

Se l'irrigatore smette di girare e/o il getto d'acqua in uscita diminuisce d'intensità sarebbe conveniente provare a pulire il filtro inferiore. Per fare questo bisogna estrarre il pistone dal corpo dell'irrigatore.

PASSAGGIO UNO

[9]

Svitate la ghiera superiore separandola dal corpo inferiore. A volte sarà necessario adoperare delle pinze per svitarla.

PASSAGGIO DUE

[10]

Una volta che la ghiera è svitata si puà estrarre il pistone dal corpo inferiore.

PASSAGGIO TRE

[11]

Il filtro posizionato nella parte inferiore del pistone può essere facilmente estratto con l'aiuto di un paio di pinze.

PASSAGGIO QUATTRO

[12]

Normalmente se la pulizia del filtro non risolve il problema di non rotazione allora l'irrigatore deve essere sostituito.

Valuta questo articolo:

Average: 3.5 (4 votes)

Link correlati

Source URL (retrieved on *03/07/2015 - 13:19*): http://www.hunterindustries.com/it/support/perche-ha-smesso-di-girare-il-mio-irrigatore-turbina

Links:
[1] http://www.hunterindustries.com/it/product/turbine/pgj
[2] http://www.hunterindustries.com/it/product/turbine/srm
[3] http://www.hunterindustries.com/it/product/turbine/pgp-adj
[4] http://www.hunterindustries.com/it/product/turbine/pgp-ultra
[5] http://www.hunterindustries.com/it/product/turbine/i-20
[6] http://www.hunterindustries.com/it/product/turbine/i-25
[7] http://www.hunterindustries.com/it/product/modelli-fuori-produzione/i-35
[8] http://www.hunterindustries.com/it/product/turbine/i-40
[9] http://www.hunterindustries.com/sites/default/files/ts_pgp_body_cap_removal.jpg
[10] http://www.hunterindustries.com/sites/default/files/ts_pgp_internal_assembly_removal.jpg
[11] http://www.hunterindustries.com/sites/default/files/ts_pgp_filter_basket_1_1.jpg
[12] http://www.hunterindustries.com/sites/default/files/ts_pgp_filter_backet_2.jpg