


**Products:** [Freeze-Clik®](#) [1]

[Solar Sync®](#) [2]

**Topics:** Troubleshooting

---

Check that the jumper tab was removed from across the two SEN terminals and also check that the sensor bypass switch on the controller is not in the Bypass position. It needs to be in the Active position to be able to utilize the sensor information. The sensor shuts the system down at 37 degrees fahrenheit.



#### Rate this Article:



Average: 3 (2 votes)

#### Related Links

---

**Source URL (retrieved on 02/26/2015 - 20:14):** <http://www.hunterindustries.com/support/why-my-hunter-freeze-sensor-not-disabling-watering-during-freeze-events>

#### Links:

[1] <http://www.hunterindustries.com/irrigation-product/sensors/freeze-clikr>

[2] <http://www.hunterindustries.com/irrigation-product/sensors/solar-syncr>

[3] [http://www.hunterindustries.com/sites/default/files/ts\\_xcore\\_jumper\\_plate.jpg](http://www.hunterindustries.com/sites/default/files/ts_xcore_jumper_plate.jpg)

[4] <http://www.hunterindustries.com/sites/default/files/freeze-clik.png>