ICC2 & PRO-C* FEATUR	EREMINDER Hunfer
Feature	Where Found
PROGRAMMABLE SENSOR OVERRIDE	Hold =, turn to Start Times
CYCLE AND SOAK	Hold +, turn to Run Times Press PRG to set Soak
DELAY BETWEEN	Hold =, turn to Run Times

Hold **+**, turn to System Off

Hold =, turn to Water Days Hold +, turn to Solar Sync **SOLAR SYNC DELAY**

STATIONS HIDE PROGRAMS

CLIK DELAY

reature	wnere round
TOTAL RUN TIME	Turn to Run Times Press ◀ from Station 1 to view
TEST PROGRAM	Hold PRG for 3 seconds
EASY RETRIEVE™	Press + and PRG to Save Press - and PRG to Restore
TOTAL RESET	Press PRG and RESET button
QUICK CHECK™	Press + _, ∢, ▶ together Press + to begin check
RUN PROGRAM	Hold ▶, press PRG to select

Whore Found

Ecoturo